Alternative Care Site – Site Visit Checklist Last revised: April 2006 Date: Contact's phone #: **SUITABILITY (0** FACILITY = not suitable, 3 REQUIREMENTS CONSIDERATIONS YES NO = very suitable) COMMENTS Multiple bus routes, W.Coast Express LOCATION ASSETS Easy to access by public transportation 3 Х 3 Parking lot and paved exterior area Х Number of parking spaces (comments only) Lots of parking space Transit access х 3 2 Transportation hindrances for any vehicle х Traffic patterns (>1 way in and out?) 2 х EXTERNAL Appears to be structurally sound STRUCTURE 3 Х Condition of exterior (comments only) Good condition Facility is currently occupied 1 Х Wheelchair accessible (ramps, not stairs) 1 Upper level is not accessible Х 2 Any obstacles from parking lot? х Condition of grounds (comments only) Good condition Loading dock (based on largest vehicle) х 1 Status of roof (e.g., leaks - comments only) Good condition Sensitive neighbours and/or abutters 3 Х

Х

х

1

0

Flood plain

fraserhealth Better health. Best in health care

DRAFT

Sample Alternative Care Site Checklist

Facility / Location: Wilson Street Recreation Centre, Port Coguitlam, BC

Facility contact: Steve or Cheryl

Assessed by: Dave Burgess and Denise McKay

Dumpsters

Storm drains

Sample Alternative Care Site Checklist – Wilson Street Recreation Centre

FACILITY REQUIREMENTS	CONSIDERATIONS	YES	NO	SUITABILITY (0 = not suitable, 3 = very suitable)	WORK REQUIRED/COMMENTS
INTERNAL STRUCTURE	General condition of interior	x		2	Good condition
AND SYSTEMS	Is facility clean and mold-free?	x		2	
	Licensure of safety systems (such as fire alarm systems, elevators, inspection certificates, etc.)	x		3	Systems are inspected and up-to-date
	Fire alarm/suppression system adequate for clinical facility use	x		3	
	Check hydro, fuel, and back-up generator system needs		x	1	Natural Gas for heat, no generator
	HVAC - type/fuel system usable and sufficient Air handlers in place and functional	x		2 2	
	Facility-wide paging/alarm system		x	3	
	Internal telephone/intercom system	×		1	In some rooms
	Communications links need to be re-established telephone, computer network and internet		x	23	Distributed in offices and computer lab
	Phone/Data ports-how many in which rooms?				In some rooms
	Adequate Lighting	х		2	
	Check electrical systems/outlets for operations and safety	x		2	
	Is water hooked-up?	x		1	Not available in all rooms
	Water heating systems operational?	х		3	
	Elevators, and are they working?		х	0	No elevator
	Much equipment/furniture to be removed?	x		1	Some furniture
	Waste Disposal and Management systems?	х		1	Bins only
	Is there a kitchen? If so-general condition and amenities - fridge/stove/sinks	x		2	Commercial kitchen
	If no kitchen - other area that could be used for food service?			0	

NOTE: This document is an **incomplete work-in-progress**, intended for the use of Fraser Health professional health care providers during an influenza pandemic. Please contact Fraser Health at <u>pandemic@fraserhealth.ca</u> if you have suggestions or for permission to use these proprietary documents.

Sample Alternative Care Site Checklist – Wilson Street Recreation Centre

FACILITY REQUIREMENTS	CONSIDERATIONS	YES	NO	SUITABILITY SCALE (0 = not suitable, 3 = very suitable)	WORK REQUIRED/COMMENTS		
INTERIOR SPACE	Number of floor levels/square footage (comments only)	2 levels, 2nd floor not accessible by elevator.					
	No. of rooms and their approx. dimensions (comments only)	6 rooms of various sizes. Capacity for 125 patients (Does not include Hockey Rink)					
	No. of washrooms (<i>male, female, and cubicles - comments only</i>)	Male: Urinals 8, Toilets 8; Female: Toilets 25					
	No. of shower facilities and locations (comments only)	Hockey rink change rooms - Many					
	Flooring (smooth, washable, and tiles sealed)	x	4	3			
	Doors/corridors wide enough for stretchers	x		1	A little narrow		
	Clean and mold/pest-free rooms	x		3			
TOTAL SUITABILIT	'Y =			68			